36 **PRATT & WHITNEY REQUIREMENT: PW QA-6071 APPLIES (CONTROL OF**

HIDDEN REQUIREMENTS AND SPECIAL IDENTIFICATION). [REV. 04/02/08]